

## Safety Gate: Rapid Alert System for dangerous non-food products

A12/01416/20
Motor vehicles
Products with serious risks
Consumer
Passenger car
ТОУОТА
C-HR HYBRID
e6*2007/46*0338*02
20SMD-051 Fr RH Drive Shaft Assy Replacement
The affected vehicles were manufactured between 5 and 21 January 2020 (K53BX), The affected vehicles were manufactured between 7 and 8 January 2020 (K54BX)
77000000 - Automotive
C-HR HV TMMT – frame code MAXH10, WMI: NMT, Range by frame number: VDS – K53BX#; VIS – 0R018635-0R022116; C-HR HV TMMT – frame code MAXH10, WMI: NMT, Range by frame number: VDS – K54BX#; VIS – 0R018864-0R0191128;
Turkey
Bulgaria
NO
Injuries
The front right-hand axle shafts may have been produced with lower material strength. If an affected vehicle is frequently driven under certain conditions where higher torque is applied to the front axle shafts, such as rapid acceleration when starting, the shaft may break, leading to loss of driving force and increased the risk of an accident.
Recall of the product from end users
Poland
No pictures are available